

BID2015-91
REPAIR #3 HIGH LIFT PUMP MOTOR OPENING DATE: 11/12/15 AT11:00AM

BID2015-87 EMERGENCY GENERATOR RADIATOR CORES REPLACEMENT FOR TRENTON SEWER UTILITY						
NUMBER OF RESPONDENTS:	6					
NAME OF BIDDER	LONGO ELECTRICAL-MECHANICAL, INC.	A.C. SCHULTES, INC.	WILLIER ELECTRIC MOTOR REPAIR CO., INC	LOCKWOOD'S ELECTRIC MOTOR SERVICE, INC.	INTEGRATED POWER SERVICES, LLC	LOUIS ALLIS
ADDRESS	1 HARRY SHUPE BLVD.	EVERGREEN AVENUE	1 LINDEN AVENUE - P.O. BOX 98	2239 NOITTINGHAM WAY	3240 S. 78TH STREET	645 LESTER DOSS ROAD
CITY, STATE, ZIP	WHARTON, NJ 07885	WOODBURY HEIGHTS, NJ 08097	GIBBSBORO, NEW JERSEY 08026	TRENTON, NJ 08619	PHILA, PA 19153	WARRIOR, AL 35180
CONTACT NAME	JOSEPH M. LONGO, PRESIDENT	AUGUST C. SCHULTES, IV, PRESIDENT	KURT SCHNEIDER	TIMOTHY DEY	JOHN HAMILTON	LONDON WILSON
TELEPHONE	973-537-0400	856-845-5656	856-627-3535	609-587-2333	215-365-1500	205-590-2986
FAX	973-537-0404	856-845-1335	856-627-5271	609-587-5780	215-365-1530	205-590-1571
E-MAIL	JLONGO@ELONGO.COM	GUS@ACSCSULTES.COM	KETSCHNER@EVERSON.NET	CONTACT@LOCKWOODSELECTRICMOTOR.COM	J@HAMILTONRPLS.COM	WILSON@LOUISALLIS.COM
STOCKHOLDER DISCLOSURE STATEMENT	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
REQUIRED EVIDENCE EEO/AFFIRMATIVE ACTION REGULATIONS QUESTIONAIRE	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
ACKNOWLEDGEMENT OF RECEIPT OF ADDENDA	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
NJ BUSINESS REGISTRATION CERTIFICATE	INCLUDED	REQUIRED FROM AWARDED VENDOR	INCLUDED	INCLUDED	INCLUDED	REQUIRED FROM AWARDED VENDOR
NON-COLLUSION AFFIDAVIT	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
AMERICANS WITH DISABILITIES ACT OF 1990 LANGUAGE	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
DISCLOSURE OF INVESTED ACTIVITIES IN IRAN	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
EQUIPMENT CERTIFICATION	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
ETHICS COMPLAINT DISCLOSURE	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
CITY OF TRENTON RESIDENT EMPLOYMENT POLICY	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED	INCLUDED
EIC	CERT#1909 EXP. 5/15/2017	CERT#1404 EXP. 6/15/2021	CERT#22828 EXP. 4/15/2018	CERT#10399 EXP. 4/15/2013	CERT#53038 EXP. 7/15/2017	REQUIRED FROM AWARDED VENDOR
CERTIFICATE OF INSURANCE	REQUIRED FROM AWARDED VENDOR	REQUIRED FROM AWARDED VENDOR	REQUIRED FROM AWARDED VENDOR	REQUIRED FROM AWARDED VENDOR	REQUIRED FROM AWARDED VENDOR	REQUIRED FROM AWARDED VENDOR
COMPLIANCE WITH 60-DAY CONTRCT EXTENSION	YES	YES	YES	YES	YES	N/A
COMPLIANCE WITH EMERGENCY SERVICES	YES	YES	YES	YES	YES	N/A
TOTAL COST TO REPAIR #3 HIGH LIFT PUMP MOTOR	\$12,290.00	\$15,368.00	\$15,696.00	\$18,945.00	\$21,825.00	\$34,862.00
FATAL FLAW	NONE	NONE	NONE	NONE	NONE	NONE